

## 7000 S. Constance (Clockwise):

1. Fireplace in Library.
2. Living Room Alcove.
3. Tile Finish under Living Room Windows.
4. Scorched Dining Room Beams needs Sanding.
5. Curved Doors to Library & Foyer.
6. 15' Ceiling in 21' x 36' Living Room with Wood Beams looking North.
7. Scorched Dining Room Walls. No Structural Damage.

